

Service Report

Site Name: Lower Longwood Lake

Date: 8/9/2019

Signature:

Email: ggslockett@gmail.com, fishonforty@yahoo.com, longwoodlakecabino
wners@gmail.com

Description of Work

Waterbody	Lower Longwood Lake					
Secchi (feet)	4	Dissolved Oxygen (ppm)	8.6	Posted Water Use Rescriptions		
Temp(F)	78	PH	6.5	Hardness	95	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Type of Service	<input type="checkbox"/> Survey <input checked="" type="checkbox"/> Treatment <input type="checkbox"/> Fountain Service <input type="checkbox"/> WQ Sample Service <input type="checkbox"/> Other Service					
Species Treated	Filamentous					
Comments	<p>Surveyed the waterbody, observed the minor growth of Filamentous Algae in the cove.</p> <p>Treated the targeted nuisance vegetation with an algaecide to help slow and control the growth.</p> <p>Overall condition of the lake is good. Past treatments are working well.</p> <p>Note: Spoke to Jeff regarding surface film on the water. Film was caused by decomposing algae.</p> <p>A.T. will return for further management.</p>					
	Aquatic Algae Present Filamentous					
	Aquatic Plants Present Filamentous					
	Service Image					

Service Report

Site Name: Lower Longwood Lake

Date: 8/9/2019

Signature:

Email: ggslockett@gmail.com, fishonforty@
yahoo.com, longwoodlakecabino
wners@gmail.com

Observed Aquatic Plants & Algae



Filamentous