

LMS Service Report

Site Name: Lower Longwood Lake

Date: 5/23/2022

Signature:

Email: ggslockett@gmail.com, fishonforty@yahoo.com, longwoodlakecabinoowners@gmail.com

Description of Work

Waterbody	<input type="text"/>				
Secchi (feet)	<input type="text" value="6"/>	Dissolved Oxygen (ppm)	<input type="text" value="9"/>	Posted Water Use Rescriptions	
Temp(F)	<input type="text" value="72"/>	PH	<input type="text" value="6.3"/>	Hardness	<input type="text" value="100"/>
Type of Service	<input type="checkbox"/> Survey <input checked="" type="checkbox"/> Treatment <input type="checkbox"/> Fountain Service <input type="checkbox"/> WQ Sample Service <input type="checkbox"/> Other Service				
Species Treated	<input type="text" value="Curly Leaf Pondweed"/>				
Comments	<input type="text" value="Observed growth of Curly Leaf Pondweed along shoreline across from boat launch, blue road cove and other spots specific to the lake all areas were treated with aquatic herbicide."/>				Aquatic Algae Present <input type="text"/>
					Aquatic Plants Present <input type="text" value="Curly Leaf Pondweed"/>
					Service Image <input type="text"/>

LMS Service Report

Site Name: Lower Longwood Lake
Signature:

Date: 5/23/2022

Email: ggslockett@gmail.com, fishonforty@yahoo.com, longwoodlakecabinoowners@gmail.com

Observed Aquatic Plants & Algae



Curly Leaf Pondweed