

## Service Report

**Site Name: Lower Longwood Lake**

**Date: 8/31/2018**

**Signature:**

**Email: nesesqpc@aol.com,  
fishonforty@yahoo.com**

### Description of Work

**Waterbody** Lower Longwood Lake

**Secchi (feet)** 4      **Dissolved Oxygen (ppm)** 9.3      **Posted Water Use Rescriptions**

**Temp(F)** 79      **PH** 6.4      **Hardness** 90       Yes     No

**Type of Service**     Survey     Treatment     Fountain Service     WQ Sample Service     Other Service

**Species Treated**    Lyngbya, Curly Leaf Pondweed  
Large-Leaf Pondweed, Eurasian Milfoil

#### Comments

Surveyed the waterbody, observed the minor/moderate growth of Eurasian Milfoil, Lyngbya, Large Leaf Pondweed, and Curlyleaf Pondweed in the Cove and sporadically throughout the lake. Treated the targeted nuisance vegetation with an aquatic algaecide and herbicide to help slow and control the growth.

A.T. will return for further management.

#### Aquatic Algae Present

#### Aquatic Plants Present

Lyngbya  
Eurasian Milfoil  
Curly Leaf Pondweed  
Large-Leaf Pondweed

#### Service Image



## Service Report

Site Name: Lower Longwood Lake

Date: 8/31/2018

Signature:

Email: nesesqpc@aol.com,  
fishonforty@yahoo.com

### Observed Aquatic Plants & Algae



Myriophyllum Spicatum



Potamogeton Crispus



Potamogeton amplifolius



Lyngbya spp.