

## Service Report


Site Name: Lower Longwood Lake

Date: 7/1/2020

Signature:

Email: ggslockett@gmail.com, fishonforty@yahoo.com, longwoodlakecabinoowners@gmail.com

### Description of Work

<b>Waterbody</b>	Lower Longwood Lake					
<b>Secchi (feet)</b>	7	<b>Dissolved Oxygen (ppm)</b>	10	<b>Posted Water Use Rescriptions</b>		
<b>Temp(F)</b>	80	<b>PH</b>	7	<b>Hardness</b>	100	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<b>Type of Service</b>	<input type="checkbox"/> Survey <input type="checkbox"/> Treatment <input type="checkbox"/> Fountain Service <input type="checkbox"/> WQ Sample Service <input type="checkbox"/> Other Service					
<b>Species Treated</b>	Filamentous					
<b>Comments</b>	<p>Surveyed the lake. Observed minor growth of decomposing Eurasian Milfoil and Filamentous Algae. Applied algaecide and aquatic herbicide to control the growth. Targeted plants are continuing to decompose. Past treatments are working well.</p> <p>Also applied, aquatic herbicide to control the growth of Large Leaf Pondweed along Yellow Road by the long dock with the yellow tent on it.</p> <p>A.T. will return for further managemen.</p>					
	<b>Aquatic Algae Present</b>					
	<b>Aquatic Plants Present</b>					
	Eurasian Milfoil Large-Leaf Pondweed Filamentous					
	<b>Service Image</b>					
						

## Service Report

Site Name: Lower Longwood Lake

Date: 7/1/2020

Signature:

Email: ggslockett@gmail.com, fishonforty@  
yahoo.com, longwoodlakecabino  
wners@gmail.com

### Observed Aquatic Plants & Algae



Eurasian Milfoil



Filamentous



Large-Leaf Pondweed